Date User: Thursday, 1/19/2006 1:47:12 PM

Linda Lacelle

## **Process Sheet**

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number

: 25578

**Estimate Number** 

: 10804

P.O. Number

: N/A

This Issue

: 1/19/2006

Prsht Rev. First Issue : NC

: NIA

: 25415

Type

S.O. No. : N/A

: NIA

Part Number

**Drawing Name** 

: Z CUSTOM

**Drawing Number** 

: UPDATE PAPERWORK

: D412-698-013/-015/-017/-019

48 28 48 35

Project Number **Drawing Revision** 

: N/A

Material

: NIA : NIA

**Due Date** 

: 1/26/2006

Qtv:

33 Um:

Each

Written By

**Previous Run** 

Checked & Approved By

Comment

**Additional Product** 

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

REMOVE FROM STOCK

D412-698-013 B 23722

D412-698-015 B 22 686

D412-698-017 B つっく54

D412-798-019 B <u>2527</u> タ B24390

ADD REVISED EASA STC EASA.IM.R.S.0079 05/05/10 TO KITS IN STOCK

2.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

ENSURE PAPERWORK AND P/N'S MATCH WITH BOXES

INSPECT WORK

3.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

**RETURN TO FINISHED GOODS** 




DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

**INSPECT LEVEL 21** 



Job Completion



Page 1

Form: rprocess